

REPRESENTATIVE INTERNAL INSPECTION EVIDENCE

22-inch Gasoline Lawn Mower Inspection Photo Record

Public summary - customer labels removed

Public-release boundary

The supplied source is a photographic record, not a signed inspection report. It does not state an inspection date, sample plan, defect count or formal disposition. This public summary therefore adds no PASS/FAIL conclusion.

Recorded product information

Website reference	DUP-LM-020	Product	Gasoline lawn mower
Engine displacement	224 cc (visible in source)	Cutting width	22 in (visible in source)
Source type	Internal inspection photo record	Formal result	Not stated
Customer / external brand	Removed for public release	Use of record	Assembly and component evidence only



Photographic coverage

- Carton and supplied-part arrangement.
- Overall product assembly, handle and control layout.
- Wheel, deck, discharge and service-point details.
- Engine, air-filter, fuel and visible maintenance components.



Current DUPOW family image; customer-branded source packaging is not shown.

Selected component evidence

	
Handle, controls and adjustment hardware.	Engine service points and visible component condition.
	
Deck, discharge and height-related components.	Representative dimensional and assembly photographs.

Interpretation

This record supports visual supplier evaluation only. Future production approval should use an order-specific inspection form with date, sampling plan, acceptance criteria, defect counts and authorized disposition.