

REPRESENTATIVE INTERNAL INSPECTION EVIDENCE

Gasoline Pressure Washer Inspection Photo Record

Public summary - source photo set dated July 2025

Public-release boundary

External-brand, importer, address, barcode, order and source-model information has been excluded. The source is a photo set without a signed sample plan or formal acceptance decision, so no PASS/FAIL conclusion is added.

Record overview

Website reference	DUP-PW-006	Product	Gasoline pressure washer
Source type	13 internal inspection photographs	Source month	July 2025
Recorded scope	Packaging, accessories and assembled unit	Sampling plan	Not stated
Formal result	Not stated	Public use	Representative visual evidence

Photographic coverage

- Packed-unit weight and opening condition.
- Included hose, gun, lance and accessory arrangement.
- Front, rear and side views of the assembled wheeled unit.
- Visible frame, engine, pump, wheels and hose management.



Current DUPOW family image; source packaging identities are not reproduced.

Selected inspection photographs



Assembled unit - front view; visible labels irreversibly obscured.



Assembled unit - side view; visible labels irreversibly obscured.



Assembled unit - rear view; visible labels irreversibly obscured.



Assembled unit - opposite side; visible labels irreversibly obscured.

Interpretation

The public record intentionally excludes the box panels because they contain customer, importer, address, barcode and source-model data. It does not replace a model-specific pre-shipment inspection.