

TWO REPRESENTATIVE INTERNAL PHOTO RECORDS

Miter Saw Inspection Photo Records

Public summary - two configurations reviewed in August 2025

Public-release boundary
Customer, external-brand, factory-model, manual, barcode, packaging and source-component identifiers have been removed. These photo sets do not contain signed sampling plans or final dispositions; no PASS/FAIL conclusion is added.

Source coverage


Website references	DUP-MS-007 and DUP-MS-010	Product	Miter saw / sliding miter saw
Record A	109 internal photographs	Record B	117 internal photographs
Source month	August 2025	Formal sample plan	Not stated
Formal result	Not stated	Public use	Visual inspection and measurement evidence

Photographic coverage


- Carton dimensions, packed weight and accessory arrangement.
- Overall assembly, guards, controls, fences and sliding mechanisms.
- Angle, alignment, laser and representative electrical readings.
- Blade dimensions plus selected motor and internal component checks.

	
DUPOW reference DUP-MS-007.	DUPOW reference DUP-MS-010.

Record A - selected evidence




Fence and table alignment view.



Laser-line positioning check.



Representative indicator measurement; source label obscured.



Motor and winding inspection.

Record A boundary

The source set documents a representative inspection sequence. External branding, packaging identifiers, manuals and blade markings have been excluded from the public release.


Record B - selected evidence



Underside and sliding-mechanism view.



Representative alignment measurement; blade identity obscured.



Laser-line positioning check.



Stator and winding inspection.

Record B boundary

The two source sets are combined in this public file for easier buyer review. They remain separate product records and do not establish equivalence between the two configurations.